## Precipitation Rate of Zirconia (Volumetric Method)





FIG. 1



## Precipitation Rate of Zirconia in Acetone KR 41B at Varying Concentrations

(Mass Accumulation Method)




FIG. 3